

Enviro-Tech



of America, Inc

Case Study:

FLORIDA APARTMENT COMPLEX LIFT STATION 96 I

BACKGROUND DATA: 50 apartment units, one office, one laundry, and one car wash. The lift station was equipped with two 5 hp grinder pumps. The station is located in an area that was difficult for a Vac Truck to get to. Also one to two days after expensive pump-out, severe grease accumulated again.

BEFORE

PROBLEM:

Solve a sewer grease problem

CONCERNS:

Floats sticking, pump-outs are expensive and not working, odor complaints

CHALLENGE:

Eliminate Fats, Oils, Grease (FOG), BOD, TSS, and ODORS without moving the problem downstream



AFTER

TREATMENT PROCEDURES:

Enviro-Tech proposed injecting **PX-700®** biostimulant and installing **System 1000** grease reduction and odor control.

RESULTS:

100% satisfaction. No grease, BOD, or TSS moved downstream and 100% of the odors were eliminated. Pump-out contract was cancelled. **PX-700®** biostimulant outperformed and cost less than all other systems.



Another Cutting Edge Product through *Biological Activity* from

Enviro-Tech of America, Inc.

Office: 239-673-8280

Fax: 239-424-8408

The F.O.G. Experts

715 NE 19th Place; Unit 22

Cape Coral, FL 33909

info@envirotechofamerica.com

www.envirotechofamerica.com



A Veteran Owned Company